

2015 NISSAN PATHFINDER S

Sport utility vehicle | 6 Cylinders | Gas

5N1AR2MM0FC658200

Country of Assembly: United States

Last Reported Odometer: 87,984 KM

One Owner™ >

No Reported Accidents™ >


LIEN CHECK




No Lien Records Found



No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)




10 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 13, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)



Lien Check

✓ No lien records found in **British Columbia**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 May 5		Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Wheel locks installed
2016 Sep 28	2,863 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Engine/powertrain computer/module reprogrammed Anti-theft/keyless remote battery replaced
2017 Feb 20	6,396 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Drive belts checked Air filter checked Tire condition and pressure checked Oil and filter changed
2017 Dec 16	15,295 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Drive belts checked Air filter checked Tire condition and pressure checked Exhaust system checked Tires rotated

ODOMETER		SOURCE	DETAILS
2020 Dec 23	56,576 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Brake pads replaced • Brake calipers cleaned/serviced • Brake rotor(s) resurfaced • Rear brake pads replaced • Brakes serviced
2021 Jan 6		J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Engine/powertrain computer/module checked
2021 Jan 28	59,423 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Drain plug gasket replaced • Maintenance reminder reset • Battery/charging system checked • Tire condition and pressure checked • Fluids checked • Cabin air filter replaced/cleaned • Lights checked
2021 Apr 16	65,203 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Drain plug gasket replaced • Maintenance reminder reset • Battery/charging system checked • Tire condition and pressure checked • Fluids checked • Brakes checked • Lights checked
2021 Aug 23	75,174 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Fluids checked • Tire condition and pressure checked • Battery/charging system checked • Maintenance reminder reset • Drain plug gasket replaced • Brakes serviced • Front brake pads replaced • Brake calipers cleaned/serviced • Brake rotor(s) resurfaced • Brake pads replaced • Rear brake pads replaced • Brake fluid flushed/changed • Tires rotated • Lights checked
2022 Dec 5	87,984 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Fluids checked • Tire condition and pressure checked • Battery/charging system checked • Maintenance reminder reset • Drain plug gasket replaced • Rear brake pads replaced • Brake pads replaced • Brake caliper(s) replaced • Lights checked



Open Recalls

Recall #: PC786 | PTHFR STP LMP SWTH NTB21-003 Recall Date: 2021 Jan 29

Recall Description

Due to the location of the stop lamp switch on the brake pedal, a chattering condition may occur in the stop lamp relay. Under certain driving conditions, such as frequent stop-and-go driving with repeated brake pedal input, the chattering can degrade the relay contact service life.

Remedy

Dealers will inspect the stop lamp switch position and set the gap to required specification. For early model year 2013 affected vehicles (prior to November 9, 2012), dealers will inspect the stop lamp switch position, set gap to required specification, and replace the stop lamp relay with a new one. For late model year 2013 to 2015 vehicles (produced after November 9, 2012), dealers will swap the stop lamp switch on the brake pedal with the Automatic Speed Control Device (ASCD) switch location on the brake pedal and then replace the stop lamp relay with a new one. This free service should take up to one (1) hour to complete but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).

Recall #: R22A2 | PATH HOOD LOCK ASSY NTB22053 Recall Date: 2022 Jun 28

Recall Description

ON CERTAIN 2013-2016 PATHFINDER VEHICLES, DUST OR DIRT CONTAMINATION MAY ACCUMULATE ON AND AROUND THE SECONDARY LATCH LEVER PIVOT JOINT. OVER TIME, THE BUILD-UP OF CONTAMINATION, COMBINED WITH A LACK OF PROPER INSPECTION AND MAINTENANCE OF THE SECONDARY LATCH (AS DESCRIBED IN THE OWNER'S MANUAL), CAN CREATE MECHANICAL BINDING THAT COULD CAUSE THE LEVER TO REMAIN IN THE OPEN POSITION AFTER IT HAS BEEN DISENGAGED. IN ADDITION, THIS CONTAMINATION CAN SCRATCH THE SECONDARY LATCH'S PROTECTIVE ANTI-CORROSION COATING, ALLOWING CORROSION OF THE BARE METAL IN THE PIVOT JOINT.

Remedy

NISSAN WILL MAIL AFFECTED OWNERS AN INTERIM OWNER LETTER THAT WILL INSTRUCT THE OWNERS HOW TO PROPERLY INSPECT THE HOOD LOCK AND SECONDARY LATCH FOR PROPER WORKING CONDITION (NO STICKING). IF THE LEVER MOVES FREELY, THE OWNER CAN CLEAN AND CONDITION THE LEVER PER THE OWNER'S MANUAL GENERAL MAINTENANCE REQUIREMENTS IN SECTION 8 MAINTENANCE AND DIY. IF THE LEVER DOES NOT MOVE FREELY, THE CUSTOMER WILL BE INSTRUCTED TO TAKE THEIR VEHICLE TO A NISSAN DEALER. THE DEALER WILL INSPECT THE HOOD LOCK AND SECONDARY LATCH AND, IF FUNCTIONING PROPERLY, CLEAN AND CONDITION BY APPLYING LUBRICANT. IF EITHER OF THESE COMPONENTS DO NOT FUNCTION PROPERLY, THE HOOD LOCK AND/OR SECONDARY LATCH WILL BE REPLACED.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 May 5		Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2016 Jul 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

	ODOMETER	SOURCE	RECORD TYPE	DEFECTS Reporter Reported
2016 Sep 28	2,863 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2016 Oct 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Feb 20	6,396 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2017 Sep 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Dec 16	15,295 KM	Ensign Pacific Chrysler Dodge Jeep Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2018 Sep 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Dec 23	56,576 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jan 6		J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jan 28	59,423 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Jan 29		NISSAN	Recall	Manufacturer Recall Issued Recall # PC786
2021 Apr 16	65,203 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Aug 23	75,174 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2021 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Jun 28		NISSAN	Recall	Manufacturer Recall Issued Recall # R22A2

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
2022 Dec 5	87,984 KM	J P S AUTOMOTIVE SERVICES North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2023 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

@Attribute.Encode(CARFAX Canada One Owner™ Badge)

Attribute.Encode(The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.)

@Attribute.Encode(CARFAX Canada No Reported Accidents™ Badge)

@Attribute.Encode(The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.



5N1AR2MM0FC658200